



### CONTROL DIMENSIONS

Profile: BUR11

Material:

NA  
NI  
NH  
FAX  
CUT

NA		NA / NI
	<=80	+/-0,1
>80	<=180	+/-0,2
>180	<=300	+/-0,3
>300	<=500	+/-0,4
>500	<=800	+/-0,5
>800	<=1000	+/-0,7
>1000		+/-1,0
NH		CSA
		+/-0,05
		+0,05/-0,15

SML Systemsoftware 3.1

29.05.2008