

CONTROL DIMENSIONS

Profile: P50-02


Material:

NA		AF2 / IF2
	<=80	-0,1
>80	<=180	-0,2
>180	<=300	-0,3
>300	<=500	-0,4
>500	<=800	-0,5
>800	<=1000	-0,7
>1000		-1,0
NH	S	CSA
<=20	-0,1	+/-0,05
>20	-0,2	

NA
NI
NH
CUT

SML Systemsoftware 3.1

02.06.2008



NA		AV / AFF / IF1
	<=100	+/-0,2
>100	<=150	+/-0,2
>150	<=200	+/-0,3
>200	<=350	+/-0,4
>350	<=500	+/-0,5
>500	<=1000	+/-0,7
>1000		+/-1,0
(NA-NI)/2		CSA / CSR
	<=5	+/-0,05
>5	<=15	+/-0,10
>15	<=20	
>20	<=30	
NH	H / H1	
<=20	-0,1	
>20	-0,2	

CONTROL DIMENSIONS

Profile: P50-01 Material: PU-RED

NA
NI
NH
CUT

SML Systemsoftware 3.1

02.06.2008