



NA		AF / AV / IV
	<=100	+/-0,1
>100	<=250	+/-0,2
>250	<=350	+/-0,3
>350	<=500	+/-0,4
>500	<=750	+/-0,5
>750	<=1000	+/-0,7
>1000		+/-1,0
(NA-NI)/2		CSA / CSR
	<=7,5	+/-0,1
>7,5	<=20	+/-0,2
>20	<=30	+/-0,3
>30		+/-0,4
	NH	
	+/-0,2	

CONTROL DIMENSIONS	
Profile: PS05	Material:
NA	
NI	
NH	
SML Systemsoftware 3.1	
23.05.2008	