



NA		NA / NI
	<=100	+/-0,1
>100	<=250	+/-0,2
>250	<=350	+/-0,3
>350	<=500	+/-0,4
>500	<=750	+/-0,5
>750	<=1000	+/-0,7
>1000		+/-1,0
(NA-NI)/2		CSA
	<=7,5	+/-0,1
>7,5	<=20	+/-0,2
>20	<=30	+/-0,3
>30		+/-0,4
<b>NHV / NH</b>		
		+/-0,2

### CONTROL DIMENSIONS

Profile: FL01A      Material:

NA  
NI  
NH