

NA		AF1 / IV
	<=40	+/-0,10
>40	<=100	+/-0,15
>100	<=200	+/-0,20
>200	<=350	+/-0,25
>350	<=500	+/-0,30
>500	<=750	+/-0,35
>750	<=1000	+/-0,40
>1000		+/-0,50
(NA-NI)/2		CSA
	<=10,0	+/-0,05
>100	<=20	+/-0,10
>20		+/-0,15
NH		
	+/-0,10	

CONTROL DIMENSIONS


Profile: R03-01

Material:

NA
NI
NH

SML Systemsoftware 3.1

30.05.2008



CONTROL DIMENSIONS

Profile: R03-02

Material:

NA
NI
NH
CUT

NA		NA / NI
	<=80	+0,1
>80	<=180	+0,2
>180	<=300	+0,3
>300	<=500	+0,4
>500	<=800	+0,5
>800	<=1000	+0,7
>1000		+1,0
H2		CSA
+0,05/-0,15		+/-0,05

SML Systemsoftware 3.1

30.05.2008