



### CONTROL DIMENSIONS

Profile: BWR07

Material:

NA		NA / M / NI
	<=80	+/-0,1
>80	<=180	+/-0,2
>180	<=300	+/-0,3
>300	<=500	+/-0,4
>500	<=800	+/-0,5
>800	<=1000	+/-0,7
>1000		+/-1,0
NA	NH / L	CSA
<=500	-0,10	-0,05
>500	-0,20	

NA  
NI  
NH  
M  
L  
L1

SML Systemsoftware 3.1

29.05.2008