



NA		AF / IFF / IV
	≤ 100	+/-0,1
>100	≤ 250	+/-0,2
>250	≤ 350	+/-0,3
>350	≤ 500	+/-0,4
>500	≤ 750	+/-0,5
>750	≤ 1000	+/-0,7
>1000		+/-1,0
(NA-NI)/2		CSA / CSR
	$\leq 7,5$	+/-0,1
>7,5	≤ 20	+/-0,2
>20	≤ 30	+/-0,3
>30		+/-0,4
NH		L
+/-0,1		+/-0,2

CONTROL DIMENSIONS

Profile: WR02A Material:

NA
NI
NH