



NA		AF2 / IV
	<=100	+/-0,2
>100	<=150	+/-0,3
>150	<=200	+/-0,4
>200	<=350	+/-0,5
>350	<=500	+/-0,7
>500	<=1000	+/-1,0
NH		CSA
	<=5	+/-0,05
>5	<=15	+/-0,10
>15	<=20	
>20	<=30	
NH	H2	
<=20	-0,1	
>20	-0,2	

CONTROL DIMENSIONS	
Profile: RS35	Material:
NA	
NI	
NH	
SML Systemsoftware 3.1	
20.05.2008	