



NA		AF1 / IV
	<=40	+/-0,10
>40	<=100	+/-0,15
>100	<=200	+/-0,20
>200	<=350	+/-0,25
>350	<=500	+/-0,30
>500	<=750	+/-0,35
>750	<=1000	+/-0,40
>1000		+/-0,50
(NA-NI)/2		CSA
	<=10,0	+/-0,05
>100	<=20	+/-0,10
>20		+/-0,15
	NH	
	+/-0,10	

CONTROL DIMENSIONS	
Profile: R04	Material:
NA	
NI	
NH	
SML Systemsoftware 3.1	
30.05.2008	